



Austin Armature Works, LP  
496 Commercial drive, Buda, TX 78610  
Phone (512)312 0088 Fax (512)312 0988

## Quote

1/2

### Customer ID

001063

### Attn

Samuel Pearson

### Quote Date

1/24/2024

### cc

### Quote Number

SRQ7720

### Job Number

SR9992

### Customer Information

CITY OF PFLUGERVILLE  
PO BOX 589  
PFLUGERVILLE, TX 78691

### Ship To Information

CITY OF PFLUGERVILLE  
PO BOX 589  
PFLUGERVILLE, TX 78691

### Quote By:

### PO #:

### RFQ #:

### Salesperson:

### Phone:

### Fax:

### Terms: Net 30

### Nameplate Information

|                |                       |
|----------------|-----------------------|
| ID             | A11363                |
| Motor-Make     | US Motor              |
| Motor-Model    | Titan II              |
| Motor-Serial # | L09 30171693-100R- 01 |
| Rating         | 600                   |
| HP Unit        | HP                    |
| RPM            | 1775                  |
| Frame          | 5012P                 |

|                |                 |
|----------------|-----------------|
| Enclosure      | WPI             |
| Rated V.       | 2300/4000       |
| Rated A.       | 132/76          |
| ODE Brg#       | Upper: 29428-EJ |
| DE Brg#        | Lower: 6219-JC3 |
| # of Phases    | 3               |
| Frequency (Hz) | 60              |

### Quote Information

|                                |   |
|--------------------------------|---|
| <b>Reason Sent For Repair:</b> | High Vibration under load ONLY<br>Teardown, inspection, & Magnetic particle Rotor Bar test  |
| <b>Cause of Failure:</b>       | Rotor Failed, as motor starts to load-up the heat affects the rotor and it start to vibrate. Gets worse the longer you run the motor. Motor passes all testing under no-load testing. Found one cracked bar and one open bar. |
| <b>Required Work:</b>          | AAW Shop SOW:<br>Provide New Custom Build US VHS Motor<br>Buyboard # 672-22<br><br>AAW FS SOW:<br>Deliver motor to site and install.<br>Setup pump height<br>Start-up support<br>Final vibration measurements.                |
| <b>Comments:</b>               | Current lead-time and parts availability are based on the time of the quote. Lead-time may change depending on the release date.  |

### Labor

### Unit Price

### Ext Price

Subtotal : 89,205.19

Tax : 0.00

Total for Quote SRQ7720 : 89,205.19

### Lead Time

14-16 Weeks

SIGNATURE: \_\_\_\_\_

DATE: \_\_\_\_\_

PO# ( IF NOT ALREADY ISSUED ):

Ship Via: \_\_\_\_\_

Your Tax ID:

Your Tax ID:

Sales Tax Code 1: No Sales Tax



Austin Armature Works, LP  
496 Commercial drive, Buda, TX 78610  
Phone (512)312 0088 Fax (512)312 0988

Customer ID

001063

Attn

Samuel Pearson

Quote Date

1/24/2024

cc

## Quote

2/2

Quote Number

SRQ7720

Job Number

SR9992

### Customer Information

CITY OF PFLUGERVILLE  
PO BOX 589  
PFLUGERVILLE, TX 78691

### Ship To Information

CITY OF PFLUGERVILLE  
PO BOX 589  
PFLUGERVILLE, TX 78691

Quote By:

PO #:

RFQ #:

Salesperson:

Phone:

Fax:

Terms: Net 30

16 Field Service and Start-up

150.00

2,400.00

Total for Labor : 2,400.00

### Material

Unit Price

Ext Price

- 1 Buyboard # 672-22, Custom Build US  
\*\*20% Buy Board discount in Ext. price\*\*  
Replacement per S/N# 30171693  
600HP  
5012P  
1800RPM  
2300/4600V  
TITAN Vertical HOLLOSHAFT  
WPI Enclosure

105,381.49

84,305.19

- 1 Freight and delivery

2,500.00

2,500.00

Total for Material : 86,805.19

Due to the Volatility of the Current Market Quotes are only Valid for 15 days until further notice.

Any & All repair jobs past 90 days are subject to scrap out and inspection billing unless arrangements have been made.

Subtotal : 89,205.19

Lead Time

Tax :

0.00

14-16 Weeks

Total for Quote SRQ7720 : 89,205.19

SIGNATURE: \_\_\_\_\_

DATE: \_\_\_\_\_

PO# ( IF NOT ALREADY ISSUED ):

Ship Via: \_\_\_\_\_

Our Tax ID:

Your Tax ID:

Sales Tax Code 1: No Sales Tax